

USB cable adapter UC1000, direct PC connection of JBC stations without USB port



Connection cable for data communication between PC (or informatics system) and the JBC stations without external USB connector.

It is used to update station software, to register temperatures and to manage station parameters.

Note: If the station has an external USB connector, you need a standard cable USB-AB to connect the station to the PC.

- Net weight: 0,05 kg (0.11lb)

- DIMENSIONS AND WEIGHT

- Package

- 277 x 73 x 50 mm / 0.12 kg.

• 10.91 x 2.87 x 1.97 in / 0.26 lb.

Item no.	WL71787
Manufacturer	JBC
Manufacturer article no.	UC1000
GPSR manufacturer data	JBC Soldering SL Ramón y Cajal 3 ES-08750 Molins De Rei www.jbctools.com
Length with packaging	277 mm
Width with packaging	73 mm
Height with packaging	50 mm
Sales unit	1 piece
Content unit	1 piece
Incl. battery	no