

Tip sleeve replacement



Tip sleeve replacement for quick change on WSP 80 / FE 75 / WSFP 5 / WXP 80 soldering irons

- For the quick change of the hot soldering tip on the soldering iron WSP 80
- When not in use, the soldering tip with the tip sleeve is placed in the safety rest.

Item no.	WL16706
Model	T0058744710
Manufacturer	WELLER
Manufacturer article no.	T0058744710N
GPSR manufacturer data	WELLER Tools GmbH Carl-Benz-Strasse 2 DE-74354 Besigheim www.weller-tools.com

Products for the electronic industry



Sales unit	1 piece
Content unit	1 piece
Incl. battery	no
Matching handpiece	FE 75, WSFP 5, WSP 80, WXP 80

