

Pointe de réparation de la série RxP, en forme de lame, largeur 15,6 mm



RxP-Blade/Quad Solder Tip Cartridges are the rework tips for the Metcal MFR-series soldering systems. The second letter in the part number designates the temperature series. RFP-Cartridges are nominally 390 °C. Metcal recommends the RFP temperature series for most applications. However, there is a higher temperature range designated RCP, nominally 450 °C, for high temperature and thermally demanding applications. Can be used with leaded and lead-free solder. The Metcal SmartHeat®-Technology will adjust the power levels during soldering to suit the application.

- pour la plupart des demandes standard
- convient aux séries MFR-1100 et MFR-2200

N° d'article

WL24738

mannequin

RFP-BL2

Products for the electronic industry



Fabricant	OKI
Fabricant Numéro d'article	RFP-BL2
Informations sur le fabricant du GPSR	OK International Ltd Eagle Close, Chandlers Ford GB-SO53 4NF Hampshire www.ok-international.com
Unité de vente	1 pièce
Unité de contenu	1 pièce
ligne de produits	Série RxP
type de pic	Rework-Lötklingen
Température max.	421 °C
Série de panne à souder	RxP
longueur de pic	9,14 mm
largeur de pic	15,6 mm
épaisseur de pic	0,5 mm
forme de pic	en forme de lame
alignement de pointe	droit
pièce à main assortie	MFR-H1_SC
Conforme aux normes ESD	non

Autres versions

N° d'article	largeur de pic
WL24737	10 mm
WL24738	15,6 mm
WL24739	22,1 mm