


Pointe de réparation de la série RxP Quad, pour QFP 44



RxP-Blade/Quad Solder Tip Cartridges are the rework tips for the Metcal MFR-series soldering systems. The second letter in the part number designates the temperature series. RFP-Cartridges are nominally 390 °C. Metcal recommends the RFP temperature series for most applications. However, there is a higher temperature range designated RCP, nominally 450 °C, for high temperature and thermally demanding applications. Can be used with leaded and lead-free solder. The Metcal SmartHeat®-Technology“ will adjust the power levels during soldering to suit the application.

- pour la plupart des demandes standard
- convient aux séries MFR-1100 et MFR-2200
- convient pour le QFP 44

N° d'article

WL24750

mannequin

RFP-QD19

Products for the electronic industry



Fabricant	OKI
Fabricant Numéro d'article	RFP-QD19
Informations sur le fabricant du GPSR	OK International Ltd Eagle Close, Chandlers Ford GB-SO53 4NF Hampshire www.ok-international.com
Unité de vente	1 pièce
Unité de contenu	1 pièce
ligne de produits	Série RxP
type de pic	Quad-Rework Lötpatronen
Série de panne à souder	RxP
Type SMT	QFP 44
forme de pic	quad
alignement de pointe	droit
pièce à main assortie	MFR-H1_SC
Conforme aux normes ESD	non

Autres versions

N° d'article	Type SMT
WL24745	PLCC 32
WL24746	PLCC 44
WL24748	PLCC 52
WL24747	PLCC 68
WL24750	QFP 44
WL24751	QFP 100
WL24749	TQFP 80